

VOLKSWAGEN

GROUP OF AMERICA

 APG
 Arizona
 Proving
 Grounds
 CONFIDENTIAL
 VERTRAULICH

Incident Documentation Sheet

Name: Petar Wolf Emp ID # 152
 Topic: Flat Tire / Replaced Shift 1s Date 4-6-25
11:12 AM

Driver was heading south on I5 about 1/4 mile before Hugh Lake Hughes Exit. Driver was in fast lane going about 65-70 mph.

Right Front tire suddenly lost pressure and vehicle swerved but driver maintained control and slowly drove to right side onto emergency shoulder.

Driver ^{stopped} was on a 6% down grade and did not feel safe to replace tire at that spot - heavy traffic.

Driver received a police escort ^{for} about 1/4 mile onto level ground and driver replaced tire with spare at that point. Erik (VW test driver) assisted driver with changing tire. Heiden

No issues changing tire and rest of shift.